

FAQ

Q: The monitor is stuck in Learn?

A: Test cam sensor on and off metal or clean off the sensor with a clean towel.

Q: The monitor keeps shutting off once I hit the reset button?

A: The Made has reached the Production Count. Set a new production counter to resume or clear out the Made.

Q: Why is the peak reading low?

A: Force sensor wire is damaged, no force while forming the part, or no material. Check force sensor.

Q: The force does not change when I turn off the feed?

A: The force may not change when material is removed if the punch and die is hitting, or the sensor may be defective.

Q: Why does the unit count with no feeds?

A: Make sure the AVG drops below the No Feed Limit with no feeds.

Q: The unit shows an error and the machine will not stop?

A: Check that the bypass relay jumper is not removed; check the relay.


ACE / INSIGHT *plus* *Installation Guide*



Anderson Controls, Inc.

Innovative solutions for Quality Control!

19176 Highway CC, Licking, MO. 65542
Phone: 847-882-0019 Fax: 847-882-1689
info@AndersonControlsinc.com



Wiring to the SMART I/O Board

OUTPUTS

- 3 Pin | 110V to 240V
- 3 Pin | 4 relays normally open, normally closed & common
- 4 Pin | wired for top light (Black, White, Blue, Brown)

INPUTS

- Digital / Proximity Sensor
Qty 5 | 12V (brown), ground (blue) & digital signal (black)
- Analog Sensor (8mm, PD or Disk Sensor)
Qty 8 | analog signal & ground

SENSOR LOCATION

Proximity Sensor
1:1 ratio

Analog Sensor
Request prints as needed